

PROVINCE OF BRITISH COLUMBIA
 Ministry of Justice
 Emergency Management BC / Office of the Fire Commissioner

FIRE REPORT - STRUCTURE

INCIDENT NUMBER: CVE 2013 01 13 12 01

Location of Incident: **2810 33RD - ST.
 VERNON BC**

of Occupants (At time of fire): **3** # of Injured: **0** # of Deaths: **0** Total Dollar Loss Estimate: \$ **s.21**

Related to Wildland Interface Fire: **NO** Property Value: \$ **s.21** Content Value: \$ **s.21** Total Value at Risk: \$ **s.21**

Code Name : Code Description

PROPERTY COMPLEX : 1700 FOOD OR BEVERAGE ESTABLISHMENT
 PROPERTY CLASSIFICATION : 1710 RESTAURANT - INCLUDES EATING PLACES SPECIALIZING IN FOOD PRI
 GENERAL CONSTRUCTION : 2000 PROTECTED COMBUSTIBLE CONSTRUCTION - WOOD PROTECTED BY PLAST
 BUILDING HEIGHT : 0010 1 STORY ABOVE GRADE
 GROUND FLOOR AREA : 2000 101 TO 500M2 (1077 - 5382FT2)
 YEAR OF CONSTRUCTION : 0066 1966 TO 1968
 MANUAL FIRE PROTECTION : 4000 EXTINGUISHER ONLY
 OUTSIDE FIRE PROTECTION : 1000 PUBLIC HYDRANT PROTECTION & FIRE DEPARTMENT
 SPRINKLER PROTECTION : 7000 NO SPRINKLER PROTECTION
 AUTOMATIC FIRE ALARM SYSTE : 1000 NO FIRE ALARM SYSTEM
 SMOKE ALARM OPERATION : 9900 NO SMOKE ALARM INSTALLED
 INITIAL DETECTION : 7000 VISUAL SIGHTING OR OTHER MEANS OF PERSONAL DETECTION (E.G. S
 TRANSMISSION OF ALARM : 1000 911
 FIRE SERVICE : 3000 COMPOSITE - CAREER & VOLUNTEER/PAID-ON-CALL FIRE DEPARTMENT
 INCIDENT : 1000 FIRE - FIRE DEPARTMENT ATTENDED
 ACTION TAKEN : 3000 EXTINGUISHED BY FIRE DEPARTMENT
 METHOD OF FIRE CONTROL : 4200 38MM OR 42MM (1 1/2" OR 1 3/4") HOSE - 1 HAND LINE
 FIRE ORIGIN, LEVEL : 3000 GROUND FLOOR, GRADE LEVEL OR GRADE TO 3M (10FT)
 FIRE ORIGIN, AREA : 2300 DINING AREA - INCLUDES MESS ROOM, CANTEEN, LUNCHROOM, CAFETE
 EXTENT OF FIRE : 2000 CONFINED TO PART OF ROOM/AREA OF ORIGIN
 EXTENT OF DAMAGE : 2000 CONFINED TO PART OF ROOM/AREA OF ORIGIN
 IGNITING OBJECT : 5100 PERMANENT ELECTRIC WIRING, CABLE (NON-ALUMINUM) - INCLUDES P
 FUEL OR ENERGY : 6000 ELECTRICITY
 FORM OF HEAT : 2000 SPARK, ELECTRICAL - INCLUDES ARC, DISCHARGE. (EXCLUDES STATI
 MATERIAL FIRST IGNITED : 9000 BUILDING COMPONENT - WALL. (EXCLUDES EXTERIOR WALL CLASSIFIE
 ACT OR OMISSION : 4400 ELECTRICAL SHORT CIRCUIT

Investigating Officer	LAFC Badge #	Telephone	ReportDate
SKOLROOD, LAWRIE	735	250-550-3563	2013-04-09

PROVINCE OF BRITISH COLUMBIA
Ministry of Justice
Emergency Management BC / Office of the Fire Commissioner

FIRE REPORT - **STRUCTURE** (NARRATIVE)

INCIDENT NUMBER: **CVE 2013 01 13 12 01**

Remarks:

SHORT IN METER BASE IGNITED WOOD COMPONENTS OF INTERIOR WALL NEXT TO IT.

Investigating Officer	L AFC Badge #	Telephone	ReportDate
SKOLROOD, LAWRIE	735	250-550-3563	2013-04-09

PROVINCE OF BRITISH COLUMBIA
 Ministry of Justice
 Emergency Management BC / Office of the Fire Commissioner

FIRE REPORT - **STRUCTURE** (NAMES)

INCIDENT NUMBER: **CVE 2013 01 13 12 01**

Name no.	: 1	Name Status	: OWNER
Name	: LOW, LAI PING	Phone	: s.22
Address	: s.22		

Claims Adjuster Name	: 1. TAYLOR / 2. SHALOVELO , DAVE, MERIL
Claims Adjuster Firm	: 1. CRAWFORD AND COMPANY ADJUSTERS / 2. SHALOVELO INSURANCE ADJUSTERS LTD.
Claim Number	: 1. s.21
Insurance Company	: 1. OPTIMUM WEST INSURANCE COMPANY / 2. PEACE HILLS GENERAL INSURANCE COMPANY
Policy Number	: 1. s.21

LOSS ESTIMATES:

Property Loss :	s.21	Content Loss : \$	s.21	Total Loss :	s.21
-----------------	------	-------------------	------	--------------	------

REMARKS:

MRS. LOW IS THE OWNER OF THE RESTAURANT BUT RENTED IT TO s.22

Name no.	: 2	Name Status	: OCCUPANT
Name	:	Phone	: s.22
Address	: s.22		

Claims Adjuster Name	:
Claims Adjuster Firm	:
Claim Number	:
Insurance Company	:
Policy Number	:

LOSS ESTIMATES:

Property Loss : \$	s.22	Content Loss : \$	s.22	Total Loss : \$	s.22
--------------------	------	-------------------	------	-----------------	------

REMARKS:

Investigating Officer	L AFC Badge #	Telephone	ReportDate
SKOLROOD, LAWRIE	735	250-550-3563	2013-04-09

